



Pt100 sensor Waterproof

Model 11-30610, in stock

Construction

Pt100 sensor built into the tip of an extruded PFA cable which yields a waterproof sensor unit. The cable is provided with a 5-pole connector.

Example of use

Temperature measurements where continuous waterproof performance is required.

Part number: 11-30610

Temperature range:

Cable -60 to 260 °C

Suitable indicator

Precision Plus (Part number: 11-30510)