



Accessories For handheld thermometers

Model 11-50000, in stock

For handheld thermometers there are several accessories available for various ways of use. See a selection in the picture and the table below!

ID No	Part number	Description	Remark
1	11-50011	Soft case.*	Space for sensor and indicator.
2	11-50150	Extension cable type K. Connectors: standard female and miniature male.	The coiled part can be extended about 1.5 metres.
3	11-50300	Paste to improve heat conduction	Tube 10 milliliters
4	11-50100	Extension cable type K. Connectors: standard female and miniature male.	Length 1 metre.
5	11-50080	Waterproof plastic bag with connection cable for sensor type K.*	Miniature connectors: male and female.
6	11-50065	Rubber boot with table support and magnetic attachment of indicator.	Suitable indicators • Therma Waterproof (11-30503) • Therma Diff (11-30502)
7	11-50075	Rubber boot.	Suitable indicators • Therma 1 (11-30501) • Precision Plus (11-30510)

*) The part number for ID numbers 1 and 5 does not include anything more than the case and the plastic bag protection respectively.