



## **Pt100 sensor Air and gas temperature**

### **Model 11-30608, in-stock**

#### **Construction**

Handheld Pt100 sensor with PA/ABS plastic handle. Electrical connection with 1 m cable and 5-pole connector. The probe consists of a stainless steel tube which at the tip is exposed to the measured media. Radiation shield covers the sensing resistor.

#### **Maximum temperature**

Probe: 200 °C

#### **Suitable indicator**

Precision Plus (Part number: 11-30510)

#### **Example of use**

Temperature measurement in air and gas.

**Part number:** 11-30608